

Contents

Preface	v
1. Introduction	1
2. Plastic Sheet, Sheet Materials, Physical Properties and Plastics – an Overview	5
2.1 Thermoforming Materials – Physical Properties	8
2.1.1 Acrylonitrile-butadiene-styrene (ABS).....	8
2.1.2 Polyvinyl Chloride (PVC)	10
2.1.3 Low-Density Polyethylene (LDPE).....	12
2.1.4 High-Density Polyethylene (HDPE)	13
2.1.5 Polypropylene (PP)	14
2.1.6 Polystyrene (PS).....	16
2.1.7 Expanded Polystyrene (EPS) (Foam).....	18
2.1.8 Polyethylene Terephthalate (PET)	19
2.1.9 Polymethylmethacrylate (PMMA)/Acrylic.....	20
2.1.10 Polyetheretherketone (PEEK).....	21
2.1.11 Polycarbonate (PC).....	22
2.1.12 Thermoplastic Olefin (TPO)	23
2.1.13 Polyphenylene Oxide (PPO)	23
2.1.14 Thermoplastic Elastomers	24
2.1.15 Biodegradable Polymer	24
2.1.16 Cyclic-olefin Copolymer (COC)	25

Update on Troubleshooting in Thermoforming

2.1.17	Polyacetal (POM)	26
2.1.18	Composites.....	26
3.	Machine Specifications – Effect of Parameters	35
3.1	Methods of Vacuum Forming	39
3.1.1	Straight Vacuum Forming.....	39
3.1.2	Vacuum (Thermo) Forming	39
3.1.3	Pressure Forming.....	41
3.1.4	Plug-assist Pressure Forming.....	42
3.1.5	Plug-assist Vacuum Forming.....	42
3.1.6	Pressure-bubble Plug-assist Vacuum Forming.....	46
3.1.7	Free Forming	46
3.1.8	Matched-die Forming	46
3.1.9	Drape Forming	48
3.1.10	Vacuum Snap-back Forming Process	49
3.2	Effect of Parameters.....	51
3.2.1	Raw Material (Plastic Sheets)	51
3.2.2	Moulds.....	53
3.2.3	Vacuum	56
3.2.4	Vacuum Holes	56
3.2.5	Plug.....	57
3.2.6	Sheet Temperature	57
3.2.7	Heaters.....	58
3.2.8	Daylight	59
3.2.9	Process Parameters	60
4.	Problem Identification – Classification– Troubleshooting – Flow Chart.....	67
4.1	Troubleshooting.....	71

Contents

4.1.1	Blisters or Bubbles	71
4.1.2	Webbing or Bridging	73
4.1.3	Excessive Sheet Sag.....	74
4.1.4	Pinhole or Rupturing.....	75
4.1.5	Excessive Post Shrinkage	76
4.1.6	Uneven Sag.....	77
4.1.7	Part Sticks to Mould.....	77
4.1.8	Stretch Marks on Part	78
4.1.9	Nipples on Mould Side of Thermoformed Part.....	78
4.1.10	Pock Marks	79
4.1.11	Poor Wall Distribution	80
4.1.12	Uneven Edges	81
4.1.13	Tearing of Sheet When Forming	82
4.1.14	Bad Definition at the Edges of the Forming Area	83
4.1.15	Glossy Spots	84
4.1.16	Part Warpage.....	85
4.1.17	Cracking in Corners	86
4.1.18	Raised Corners	87
4.1.19	Surface Markings	88
4.1.20	Parts in the Corners Too Thin	89
4.1.21	Folds, Webbing or Wrinkles	90
4.1.22	Part Deforms During De-moulding	90
4.1.23	Poor Part Detail.....	91
4.2	End-product Problems	91
4.2.1	Migration of Additives	91
4.2.2	Melt Failure During Thermoforming.....	93

Update on Troubleshooting in Thermoforming

4.2.3	Blue Coloured Dots	93
4.2.4	Shrinkage	94
4.2.5	Sheet Pull-out	94
5.	Optimisation of the Production	97
6.	Case Studies	103
6.1	Case Study 1	104
6.2	Case Study 2	106
6.3	Case Study 3	107
7.	Conclusion	109
	Abbreviations	113
	Author Index.....	115
	Subject Index.....	121